53 Warminster Road

Structural Repairs Works

External Areas

- Windows – Existing UPVC windows were washed down using UPVC cleaner
- Masonry Window Cills – Dulux Trade Weathershield Masonry Smooth (Pure Brilliant White)
- Roof Tiles – Spanish Slates (Cupa 50)
- Facias – Eurocell 250mm wide Black Ash
- Soffits – Eurocell 350mm wide White Eurosoffit
- Gutters – Deep Flow Gutter 115mm

Internal Areas

- Steelwork Intumescent Coating – Firetex FX5090 (white)
- Loft Access door – Manthorpe Insulated Drop Down door 686 x 856mm

All refurbishment works carried out by Client's own contractors, Collins Contractors responsible for the structural repairs and re-instatement of walls, ceilings and floorboards that were removed by us to carry out structural works.