Silivri Veteriner Klinigi

Yeni Mahalle Deha Sk. No:14 Silivri
Telephone: 0212 727 47 51
Fax:
Website: www.silivriveterinerklinigi.com
Medical Director: UGUR BAZAN

Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal: Dog(>15kg.)
Animal ID: PROSV100076
DOB: 19/09/2017 **Age:** 8Years
Gender: Male **Accession #:** PROSV15910

Canine(>15kg) Abdomen

Exam Date: 15/07/2026
Location: ISTANBUL
Ref.Physician: UNKNOWN^UNKNOWN
Equipment Used: Mindray Vetus 8

Clinical Indications & Data


Study Description: CARDIOLOGY-US


Height: 0.00cm **Weight:** 0.00kg


Sterilisation: Unknown


Abdomen - 1 / 7 Page

Ultrasound Image











Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal ID: PROSV100076 **DOB:** 19/09/2017 **Age:** 8Years **Gender:** Male


Canine(>15kg) Abdomen


Exam Date: 15/07/2026 **Location:** ISTANBUL **Ref.Physician:** UNKNOWN^UNKNOWN


Ultrasound Image
















Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal ID: PROSV100076 **DOB:** 19/09/2017 **Age:** 8Years **Gender:** Male


Canine(>15kg) Abdomen


Exam Date: 15/07/2026 **Location:** ISTANBUL **Ref.Physician:** UNKNOWN^UNKNOWN


Ultrasound Image
















Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal ID: PROSV100076 **DOB:** 19/09/2017 **Age:** 8Years **Gender:** Male


Canine(>15kg) Abdomen


Exam Date: 15/07/2026 **Location:** ISTANBUL **Ref.Physician:** UNKNOWN^UNKNOWN


Ultrasound Image
















Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal ID: PROSV100076 **DOB:** 19/09/2017 **Age:** 8Years **Gender:** Male


Canine(>15kg) Abdomen


Exam Date: 15/07/2026 **Location:** ISTANBUL **Ref.Physician:** UNKNOWN^UNKNOWN


Ultrasound Image
















Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal ID: PROSV100076 **DOB:** 19/09/2017 **Age:** 8Years **Gender:** Male


Canine(>15kg) Abdomen


Exam Date: 15/07/2026 **Location:** ISTANBUL **Ref.Physician:** UNKNOWN^UNKNOWN


Ultrasound Image
















Name: MUZEYYEN ERTURK,OSCAR,PROSV15910
Animal ID: PROSV100076 **DOB:** 19/09/2017 **Age:** 8Years **Gender:** Male

Canine(>15kg) Abdomen

Exam Date: 15/07/2026 **Location:** ISTANBUL **Ref.Physician:** UNKNOWN^UNKNOWN

Ultrasound Image





Comments:

Sol ventrikul sistolik ve diastolik fonksiyon normaldir.
LA/Ao orani normal.
Epss normal.
Pulmoner arter kapagi stabil calikmaktadir.
Aort kapagi stabil calismaktadir.
Trikuspit kapakda regurgitant akim izlnmemeistir.
Perikard duzenlidir.
Pleural efuzyon gozlenmemistir.
Btin Usg;Idrar kesesi duvar kalinligi normal.Kese icerisinde sediment gozlenmedi.
Her 2 bobrek normal gorunumde.
Safra kesesinde az miktarda camur gozlendi.Karaciger normal ekojenitededir.
Dalak normal ekojenitededir.
Sonuc;Normal Eko bulgulari, safra kesesinde az miktarda camur mevcut.

Signature(seal): **Date Signed:**