
CLUTTONS
Chartered Surveyors • Property Consultants

Project: 53 WARMINSTER RD, LONDON SE25


Job No.	27266.03
By	M.L.
Date	22.2.23
Sheet	S-SK54

CRACK REPAIR AT BRICKWORK FLANK WALL

1. EXISTING BRICKWORK AT CRACK LOCATION



2. BRICK STITCH & HELIFIX REPAIR



NOTES

1. REFER TO S.SK53 FOR LOCATIONS REQUIRING CRACK REPAIR AS PER THIS SHEET